

Datasheet

GPM 1 SA Semi-Automatic Quick Change Mounting Plate

Item number: 02.14.332



- Automatically couples air and vacuum lines
- Prevents mixing up of air and vacuum lines during tool changes
- Must be used with a SWM SA Quick Change Chuck

Technical data

Description	Unit	Value
Length (A)	in	3.94
Length (B)	in	2.76
Length (# of Ports)	in	0.28
Thread	in	M5
SWM chuck	-	SWM 1 SA