

Datasheet

GPM 3 SA Semi-Automatic Quick Change Mounting Plate

Item number: 02.14.338



- Automatically couples air and vacuum lines
- Prevents mixing up of air and vacuum lines during tool changes
- Must be used with a SWM SA Quick Change Chuck

Technical data

Description	Unit	Value
Weight, max.	oz	127.86
Length (A)	in	9.84
Length (B)	in	3.94
Length (# of Ports)	in	0.39
Thread	in	G 1/8
SWM chuck	-	SWM 3 SA