

# Datasheet

## GPM 2 SA Semi-Automatic Quick Change Mounting Plate

Item number: 02.14.334



- Automatically couples air and vacuum lines
- Prevents mixing up of air and vacuum lines during tool changes
- Must be used with a SWM SA Quick Change Chuck

### Technical data

Description	Unit	Value
Length (A)	in	6.30
Length (B)	in	2.36
Length (# of Ports)	in	0.28
Thread	in	G 1/8
SWM chuck	-	SWM 2 SA